

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report April 21st 1958 When handed in at Local Office 19 Port of MONTREAL
 No. in Reg. Book 16586 Survey held at Kingston Date, 8th April First Survey 8th April Last Survey 17th April 1958
 (No. of Visits TWO)

on the Steel "KEYNOR"
 TONNAGE:—
 GROSS 1806 Built at Londonderry By whom N. of Ireland S.B. Co. Ltd. When 1914 month 6
 UNDER DK. Owners La Verendrye Line Limited.
 NET 1090 Managers - Port belonging to Montreal

Surveyed Afloat or in Dry Dock? Afloat Name of Dock MR Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 11496 Port MR

REPAIRS, OR EXAMINATION AS PER RULE FOR

YES

NOW LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
*100A1 with fbd. For service on the River St. Lawrence & Great Lakes also on the Gulf of St. Lawrence 1st April to 30th November. 11,56	*LMC 4,57
Lake S.S. 4,57(dr) 9,48	MBS 2,57
A.S. 4,57	TS(CL) 11,56
	SPS 2,55

ITEMS EXAMINED AND CONDITION FOUND, ETC.

		A.S. 4,57		ITEMS EXAMINED AND CONDITION FOUND, ETC.	
Holds including bulkheads, inner bottom plating, etc.		Good			
Bilges & ceiling.		- do -			
Tween decks.		- do -			
Deck & deck erections.		- do -			
Machinery Space.		- do -			
Under Engines & Boilers.		- do -			
Masts, Rigging & Outfit.		- do -			
Windlass & Hawse Pipes.		- do -			
Air & Sounding Pipes with closing appliances.		- do -			
Pumps and Pumping arrangements outside machinery space.		- do -			
Steering arrangements including gear.		- do -			
W.T. Doors & Sluice valves.		- do -			
Ventilator coamings with their closing appliances.		- do -			
Hatchway coamings with their closing appliances.		- do -			
Casings, companionways and their closing appliances.		- do -			
Superstructure bulkheads with their closing appliances.		- do -			
Guard rails & freeing ports.		- do -			
Overboard discharges, also ash chutes & other shell openings.		- do -			
		EXAMINED	TESTED	CONDITION	
Peaks		Yes	Yes	Good	
Side Tanks in hold.					
Deep Tanks					
Cargo Tanks		} (Tankers)			
Cofferdams					
Pump Rooms					
Has a Load Line Annual Survey been held?		Yes			
Has a Grain Survey been held?		Yes			
Has a Damage Survey been held?		No			

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, I,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,58

Survey Fee \$ 36.00

Special Damage or Repair Fee (if any) \$ 4.00

Travelling Expenses \$ 25.00

Second Surveyor's Fee (if any) \$

Committee's Minute

Character Assigned

Fees applied for,

USSA MAY 1 1958

THURSDAY 22 MAY 1958

AS 4.58
MBS 2.58

(with endorsement)

Surveyor to Lloyd's Register of Shipping.
(Wm. HEATLIE)



© 2020

Lloyd's Register
Foundation

003321-003327-0167

Noted
for
Header

