

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Stb T.S. NEPTUN*

Rpt. *Ham*

No. *16808*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. *92.16*

Depth "d" *✓*

Framing: Table No. *✓*

Description *Longitudinal framing*

Longitudinal No. *39375*

Proportions

Length

12-17

Depth =

Deck Sheerstrake *as approved.*

This case was before the Committee on the 7th inst but through an oversight the change made at the owner's request in the description of the class was not brought out.

~~This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed~~

✠ 100 A.1. (Steel) "Carrying Petroleum in Bulk", "Cable vessel", "Cylindrical Tanks"
2 DK (Stl) - Well frame, Longitudinal Framing.
Cell DB, E+B. Bunker 118, 210, 940 t, D.T. 39' 34 1/2", F.P.T. 62", A.P.T. 92".
F.K, 10 B.H. *pt cem, pt asp, Lloyds A+C.P.*
P 143', F 78' machy apr.

Mly

BH



© 2020

Lloyd's Register Foundation

003333-003340-0232

11.5.26