

Sm. 1.1.18.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stl S^{M/V} PAUA*

Report *Sls* No. *46775*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey

1st Entry

When due

Revised Rules

✱ 100 A. I. (Steel). Carrying Petroleum in Bulk
 1 D¹ (Stl). Longitudinal framing at bottom and at deck
 Cell D.B a 48' + 20' qqt, F.P.T. 2qt, A.P.T. 27t.
 F.K, Q.B.H, pt Cen, Lloyd's A.C.P.
 P 67', F 41', "machy apr"



© 2020

Lloyd's Register
 Foundation

003385-003390-0088

Bracket Floors, breadth and thickness at
 middle line.....

spacing.....

Forecastle Deck