

Ship's Name *ANTAR*

Extract from Freeboard Verification of Marking Form
received from the *Sunderland* Surveyors,
dated *22.1.41*

Moulded depth	<i>29</i>	ft.	<i>0</i>	ins.
Corresponding draught	<i>25</i>	ft.	<i>10³/₄</i>	ins.
Moulded depth as shown on draught sheet	<i>29</i>	ft.	<i>0</i>	ins.
Tropical freeboard	<i>2</i>	ft.	<i>9¹/₄</i>	ins.
Summer "	<i>3</i>	ft.	<i>3³/₄</i>	ins.
Winter "	<i>3</i>	ft.	<i>10¹/₄</i>	ins.
W.N.A. "	<i>✓</i>	ft.	<i>✓</i>	ins.
Fresh Water allowance			<i>6³/₄</i>	ins.

Marked from ~~main~~ steel upper deck.

*
Checked by *Hew*
Date *16/2/41*



© 2020
Lloyd's Register
Foundation

003421-003428-0182