


Ship's Name ~~SS~~MS IRINI'S BLESSING

~~SSXXXXXXXXXXXXXXX~~

Port of Mestre (Venice) Rpt. No. 0830

	<u>Examined & condition</u>	<u>Examined & condition</u>
In dry dock from	24th March, 1963	* Air & sounding pipes good (on deck)
" " " to	24th March, 1963	Doublers under " " not examined
Shell plating	efficient	Steering arrangements (main) good
Sternframe	good	" " (aux) good
Rudder	good	Windlass good
Was rudder lifted?	no	Masts & rigging good (from deck)
Plating, etc. in way of shell openings	efficient	Hand pumps & suctions good
Side scuttles & deadlights	good	W.T. doors good
Overbd. scuppers & discharges	good	Bulwarks, freeing ports, etc. good
F.P. spaces	good	
Chain locker	not examined	Summer freeboard as verified 2' 4"
A.P. spaces	good	
Engine space	not examined	
Boiler space	not examined	<u>EQUIPMENT:</u>
Under E. & B.	not examined	Equipment letter b +
Coal bunker	none	Fee ltr., if diff. from eqpt. ltr. -
Tunnel & well	good	Anchors: No. on board 3 B
Cement, asphalt, etc., on btm. shell	good	State if ranged not ranged
Weather decks	good	Length on board stated correct
* Casings	good	Cables { Mean dias. range from - to - Rule length - Dia
* Deckhouses	good	
* Superstructures	good	Mooring ropes sufficient
* Skylights	good	
* Companionways	good	
* Hatchways	good	
* Ventilators	good	
Other items:	fore and aft store spaces.	

* These items to include their closing appliances
Where a part Special Survey and, say, Dry Docking Survey are held at the same time, the items for SS should be marked "For SS"



© 2020
Lloyd's Register of Shipping
Surveyor to Lloyd's Register of Shipping
(P. Cesari)

HOLDS & 'TWEEN DECKS:		Examined & condition	TANKS:	Examined & condition	Tested & condition
No. 1	Hold	not examined	F.P. tank	not examined	tested = good
"	'Tween decks	satisfactory	A.P. tank	satisfactory	not tested
			D.B. tanks & c/dams	not examined	not tested
No. 2	Hold	satisfactory			
"	'Tween decks	satisfactory			
No. 3	Hold	not examined	O.F. bunkers	not examined	not tested
"	'Tween decks	satisfactory			
			Settling tanks	not examined	not tested
No. 4	Hold	not examined			
"	'Tween decks	satisfactory			
			Deep tanks	not examined	not tested
No. 5	Hold	satisfactory			
"	'Tween decks	satisfactory	Side tanks	not examined	not tested
No. 6	Hold		Wing tanks	not examined	not tested
"	'Tween decks				
			Other tanks:	not examined	not tested
	Cargo battens	none			
	Ceiling, etc.	satisfactory			



© 2020

Lloyd's Register
Foundation