

25 JUL 1962

Received from Chief Ship Surveyor.....

NAME "A V O N Y" REPORT KEL 3256  
EA

standing Conditions of Class: SUBJECT to shell plate D.4 (s.s.f) being  
specially examined and dealt with as necessary by the Special Survey.

Appendix. (~~XXXXXXXXXX~~ None)

e of Present Survey: (Afloat and in dry dock)

Docking: Deferred repairs to grounding damage.

Recommendation:

SUBMITTED record of DS 6,62 be assigned, subject as above  
and to indented bottom shell plates A.12,13,14 & 15, B.7,8,  
9,10,11,12,13 & 14, D.10,12 & 13, E.9 & 10 (s.s.from fwd),  
keel plate No.13, C.15 and E.9 (p.s) being specially examined  
and dealt with as necessary by the Special Survey.

DS 6,62 Subject.



© 2020

Lloyd's Register  
Foundation

003429-003433-0011