

Received by Chief Ship Surveyor _____ Received from Chief Ship Surveyor _____
 VESSEL'S NAME Stl & KYLOE * Rpt. hdb No. 13994

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long Transverse No. 7167 Depth "d" 20.42
 Framing: Table No. ✓ Description Bull angle frames as approved
 2nd Longitudinal No. 20980 Proportions Length 12.97
 Depth = _____
~~Deck~~ Sheerstrake as approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel).

1 D^k (Stl).

Cell D.B. 205' 681t, D.T.a 56' 255t, F.P.T. 164t, A.P.T. 100t.

F.K. 6 B.H. cm, Lloyds A.V.P.

P 23' B 50' F 23'

TRUNK IN WELLS.



[Signature]
7.3.30



© 2020

Lloyd's Register Foundation

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

003434-003443-0366