

3m, 5, 21.

1

How "Wenterswijk"

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Steel S.S. "Dunstaffnage" Report Yrk. No. 18023

For the CHIEF SHIP SURVEYOR ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause of causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey First Entry. When due _____

✱ 100A1. (Steel)

2 Dks (Steel)

Cell DB. 331' 1031 t. DTa 30' 780t. APT 20t.

FK. " Tween deck bulkhead in after hold dispensed with "

5 BH to Upper DK. 1 BH to 2nd DK only

(Bulkhead letter from bureau attached)

Cem. Lloyds ATCP. P 34' B 113' F 44'



© 2000 R.K.M

14.9.22

Lloyd's Register Foundation

29.3
\$ 5.9
23.11

003458-003468-0145