

Received from Chief Ship Surveyor

22 MAY 1959

SHIP'S NAME "ADELFOTIS 11"

REPORT

Pir. No. 7995

GB

standing Conditions of Class:

SUBJECT to set up bottom plating etc. (s.s.a & f) and indented side shell plating (p & s) also horizontal stiffeners of cargo hatch coaming (wasted) being examined and dealt with by next Special Survey.

Alteration of Certificate (~~As before~~ or None)

Location of Present Survey: (Afloat and in dry dock)

SPECIAL SURVEY (C) due 12,58: Conversion to O.F. in accordance with approved plan: Damage repairs including conditions of class.

Recommendation:

SUBMITTED record of 'DS 4,59' and Notation of 'SS Pir. 4,59' be assigned as recommended, but without special conditions.

DS 4,59  
SS Pir. 4,59 Without.

INSERT IN R.B.

O.F. 4,59

MTs O.F.

NOTED FOR  
TESTING



© 2020

Lloyd's Register  
Foundation

003474-003478-0110