

by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME

Anteo

Rpt.

*Tri:
Gen*

No.

10664

13395

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/82.

Type of Engine

Cil Engine 2 S.C.P.A.

6 Cy. 29 1/2" - 49 3/16"

911 NHP.

If Boilers fitted with forced draught

No main boilers

Tail Shaft. If fitted with a continuous liner

Yes

If fitted with an outside gland of

No

approved type

The main & auxiliary engines have been constructed under special survey. The shafting, air receivers, electrical equipment, pumping arrangements & decker boilers have been examined, and found to be in accordance with the approved plans.

This vessel's machinery appears to ^{be} have been built in accordance

with the Rules and the approved plans, and it is submitted she is

eligible to be classed *LMC 11.34*

2 DB 156 etc.

[Signature]
21/1/35



© 2020

Lloyd's Register Foundation



003487-003494-0065