

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. S. S. TAIPING Rpt. H. Kg No. 5952**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long
 Transverse No. 9100 Depth "d" 14.75
 Framing: Table No. ✓ Description Bull angle frame as approved
2 Longitudinal No. 25900
 Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.46}{}$
 Deck Sheerstrake as approved
Revised Rules



This vessel appears to have been built in accordance with the Revised Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel)

2 D^{ks} (Steel - Upper D^k beams)

Cell D.B. 297 596 t, tanks at sides of tunnel 74t, F.P.T. 55t, A.P.T. 34t.

F.K, 7 B.H (1 B.H. to 2nd D^k), Cem, Lloyd's A.C.P.

P. B 225', F 87'.

003503-003512-0214