

5m, 7, 31.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel Screw "PLOVER"

Report

Gls. (Dun)

No. 57101

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First Entry

When due

--

\*100A1


1 Dk.

Cell. DBuE 14' f 46' 63t, FPT 35t, APT 12t.

FK, 3 BH, Cem. Lloyd's A &amp; CP.

P 47' F 63'

Machy. aft.



© 2020

Lloyd's Register  
Foundation

This is a sister ship to the "MALLARD"

003503-003512-0245

Height of Brackets at side above  
base line at toe of frame .....

Middle Line Keelson, on Floors, Angles.)

30

app. 16

4' 3"

29"

Spacing