

REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report April 21st 19 58 When handed in at Local Office 19 Port of MONTREAL
 No. in Reg. Book 25178 Survey held at Prescott, Ont. Date, First Survey 25th March Last Survey April 16th 19 58
 (No. of Visits TWO)
 on the Steel S.S. "R.H. MARSHALL"

TONNAGE:— Built at Walsend-on-Tyne By whom Swan, Hunter & Wgham. Rchdsn. When 1929 4 month
 GROSS 1926 Owners Colonial Steamships Limited.
 UNDER DK. Managers - Port belonging to -
 NET 1147

Surveyed Afloat or in Dry Dock? Afloat Name of Dock - Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. - Port -

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

| CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys. | Machinery and Boiler Surveys (Including date of N.B., if any). |
|---|---|
| BS* Great Lakes & River St. | MBS* 10,55 |
| Lawrence service. 10,55 | MBS 2,57 |
| Lake S.S. 10,55 | TS(CL) 10,55 |
| A.S. 4,57 | SPS 2,50 |

| | ITEMS EXAMINED AND CONDITION FOUND, ETC. |
|---|--|
| Holds including bulkheads, inner bottom plating, etc. | Good |
| Bilges & ceiling | - do - |
| Tween decks. | - do - |
| Deck & deck erections. | - do - |
| Machinery Space. | - do - |
| Under Engines & Boilers. | - do - |
| Masts, Rigging & Outfit. | - do - |
| Windlass & Hawse Pipes. | - do - |
| Air & Sounding Pipes with closing appliances. | - do - |
| Pumps and Pumping arrangements outside machinery space. | - do - |
| Steering arrangements including gear. | - do - |
| W.T. Doors & Sluice valves. | - do - |
| Ventilator coamings with their closing appliances. | - do - |
| Hatchway coamings with their closing appliances. | - do - |
| Casings, companionways and their closing appliances. | - do - |
| Superstructure bulkheads with their closing appliances. | - do - |
| Guard rails & freeing ports. | - do - |
| Overboard discharges, also ash chutes & other shell openings. | - do - |

| | EXAMINED | TESTED | CONDITION |
|--|----------|----------------|-----------|
| Peaks | Yes | | Good |
| Side Tanks in hold. | | | |
| Deep Tanks | | | |
| Cargo Tanks | | | |
| Cofferdams (Tankers) | | | |
| Pump Rooms | | | |
| Has a Load Line Annual Survey been held? | No. | C.G. Load Line | |
| Has a Grain Survey been held? | Yes | | |
| Has a Damage Survey been held? | No. | | |

General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4,54" or "to remain as classed and to have record of docking, 1,54 and the notation Lake S.S. 4,54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,58

Survey Fee \$ 66.00
 Special Damage or Repair Fee (if any) 4.00
 Travelling Expenses \$ 25.00
 Second Surveyor's Fee (if any) \$ -
 Committee's Minute THURSDAY 22 MAY 1958
 Character Assayed As above

Fees applied for, MAY 1 1958

W. Heatlie
 Surveyor to Lloyd's Register of Shipping.
 (Wm. HEATLIE)



Noted for Header

003556-003566-0153

| | | ITEMS EXAMINED AND CONDITION FOUND, ETC. | |
|---|--|--|----------------|
| IN DRYDOCK Outside shell, Sternframe & Rudder | | | |
| Bunkers - coal | | | |
| Striking plates | | | |
| Chain locker & Cable holdfasts | | | |
| Equipment letter | | | |
| Anchors, No. of | | | |
| Cables (State if now ranged) | | | |
| Length on board | | Fathoms | Mean diameter. |
| Rule length | | Fathoms | Diameter. |

It should be stated whether it was considered necessary to test any tanks at this time.

| TANKS | EXAMINED | TESTED | CONDITION |
|--------------------------|----------|--------|-----------|
| O.F. Tanks. | | | |
| Double bottom tanks. | | | |
| Feed water & F.W. tanks. | | | |

Undocking Date.....

Was it considered necessary to drill the plating at this time?

General Notes on Survey, not included above.....

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

ANCHORS.

| Number of Certificate. | Anchors. | WEIGHT EX. STOCK. | | WEIGHT OF STOCK. | | TEST PER CERTIFICATE. | | WEIGHT REQUIRED BY RULE. | | Description of Anchor. | Makers. | Where and when tested and Surveyor. |
|------------------------|----------|-------------------|--|------------------|--|-----------------------|--|--------------------------|--|------------------------|---------|-------------------------------------|
| | | lb. | | lb. | | lb. | | lb. | | | | |
| | | | | | | | | | | | | |

CHAIN CABLES.

| Number of Certificate. | Length and size supplied. | | Test per Certificate. | | WEIGHT OF CHAIN CABLE. | | Length and size per rule. | | Description. | Makers of Cables. | Where and when tested and Surveyor. |
|------------------------|---------------------------|-------|-----------------------|-----------|------------------------|-----------|---------------------------|-------|--------------|-------------------|-------------------------------------|
| | Length. | Diam. | Statutory. | Breaking. | Supplied. | Per Rule. | Length. | Diam. | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

Stream Chain }
or Wire }



© 2020
Lloyd's Register
Foundation