

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME *S.S. "RIVER ELY"*

Rpt. *DUN.*

No. *8369*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *44.54.*

Depth "d" *11.96.*


Rating: Plate No. *3.*

Description *Bull Angle*

Longitudinal No. *8418*

Proportions Length = *12.99.*  
Depth =

*Upper* Deck Sheerstrake *as approved.*



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100 A1 (Steel)

*1 D<sup>+</sup> (Steel) Well D<sup>+</sup>*

*bell D.B. f. 119' 17 1/2 FPT 60t APT 5t*

*F.K. 3 B.H. Cem. Lloyd's A&CP. Q 109' B 11' F. 24'*

*MCHY AFT.*

Certificate of Classification, to be endorsed "no battens not fitted," and the same to be printed in the Register Book.



© 2021

Lloyd's Register Foundation

003567-003571-0253

*W.L. 20.5.22.*