

REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship NYON Official Number - Port of Registry Basle  
Place of Survey Adelaide Dates of Survey 5 - 13 Apr 55 Date of last Load Line Survey 8 May 54

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners			
Beams			
Fore and afters			
*Covers			
*Tarpaulins			
(State number per hatchway)			
*Cleats and battens			
Lashings and their fittings			
Wedges			
(Is supply, including spares, adequate?)			
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	Good ✓		
Beams	"		
Fore and afters			
*Covers	Good ✓		
*Tarpaulins	" two		
(State number per hatchway)			
*Cleats and battens	Good ✓		
Lashings and their fittings	"		
Wedges	"		
(Is supply, including spares, adequate?)	adequate		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings	Good ✓		
Beams	"		
Fore and afters			
Covers	Good ✓		
Tarpaulins	" two		
(State number per hatchway)			
Cleats and battens	Good ✓		
Wedges			
(Is supply, including spares, adequate?)	adequate		
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	"		
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good ✓		
Closing arrangements	"		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good ✓		
7. Within partially enclosed superstructures.			
Closing arrangements			
MACHINERY CASINGS.			
8. Casing Top.			
Fiddley openings, their covers and fastenings	Good ✓		
Skylights, their fastenings, covers and lashings			
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	Good ✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings.	Good ✓		
11. Within partially enclosed superstructures.			
Doors and fastenings			
12. FLUSH BUNKER SCUTTLES and chain attachments			
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers	Good ✓		

\* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).



Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.</b>			
Forecastle	Good		
Bridge, fore end	Good		
Bridge, after end	Good		
Poop	Good		
<b>15. GANGWAY, CARGO AND COALING PORTS.</b>			
In ship's side and superstructures	-		
<b>16. SCUPPERS AND SANITARY DISCHARGE PIPES.</b>			
Valves	Good		
<b>17. SIDE SCUTTLES AND DEADLIGHTS</b>			
	Good		
<b>18. GUARD RAILS</b>			
	Good		
<b>19. PROTECTION AND ACCESS TO CREW'S QUARTERS.</b>			
Gangways	-		
<b>20. LIFELINES (fittings and material)</b>			
	Fine, good		
<b>21. FREEING PORTS.</b>			
Shutters	-		
Protection bars	-		
<b>22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.</b>			
Fittings or appliances	-		
<b>23. ITEMS NOT INCLUDED IN THE FOREGOING.</b>			
<b>24. LOAD LINE MARKS</b>			
	correctly marked freshly painted		

**Certificate A. To be signed by Surveyor in respect of a partial or complete survey.**

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
all	B. E. Hall	Adelaide	13 April 1955

**Certificate B. To be signed by Surveyor completing the survey.**

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor B. E. Hall Place Adelaide Date 13 April 1955

Signature B. E. Hall

Date 13 April 1955

Fee £ 21 - 0 - 0

Number of Visits Two

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.