

For the information of Surveyors and the Committee only.

Received at _____ Office _____ 19

Lloyd's Register of Shipping.

(Report on Vessel No. _____ Port _____)

No. 77. SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~ Castings, manufactured by Messrs. Burmeister & Wain of Copenhagen for the Vessel No. 348, being built by Messrs. Burmeister & Wain of Copenhagen have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects.

One sternpost.

Copenhagen, 1st July 1927.

A. S. Jacobsen

Lloyd's
No. 77.
2.12.26.

REGISTER OF SHIPPING

	1 / STERN FRAME ^{Post}	RUDDER FRAME.	STEM.
Material*	S. M. J. Steel.	/	/
Made by †	Hydraulic forged.		
Dimensions	Finished.		
Process on Inspection	29/10, 10/11, 2/12. 26.		
When Inspected			
CASTINGS.			
Tests on Standard Test Pieces.			
Tensile Test—	28.1		
Weight per square inch	2" 33.7.		
Percentage extension per cent.			
90° Bending Test—	120° good.		
Angle before fracture	45° good.		
Rebore Test—	satisfactory.		
Height from ground ...			
Tempering Test—			
Examined made according to Rules and found satisfactory ...			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

Drilling test - good.

Fee (if any chargeable) £ :
To be paid at

If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

22. T. †. State if annealed *yes.*



© 2020

Lloyd's Register Foundation

003625-003630-0147