

Name of Owners

Date of Verification

10.12.28

1500,2,24.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stl S^M "DEIDO"*Report *Stl* No. *47672***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey

P. Entry

When due

Revised Rule

✠ 100 A.I. (Steel). "With freeboard Carrying vegetable oil in deep tanks
 2 D^K (Stl) + Shelter D^K (Stl).
 Cell D.B. 284' 834t, D.Ts a 58' 628t, F.P.T. 91t, A.P.T. 100t.
 F.K, 6 B.H (Coll B.H to Shelter D^K, 5 B.H to 2nd D^K). ft cm, Lloyd's A/C.P.
 P 37' F H1'.



© 2020

Lloyd's Register
Foundation
20.12.28
MC

Freeboards compared and found correct by

Date

005726-005726-0174