

Hamburg Report Nr. 2107
 For the information of Surveyors and the Committee only.

Received at _____ Office _____ 10

Lloyd's Register of Shipping.

No. 72/4888. (Report on Vessel No. _____ Port _____)


3924. SHIP ~~FORGINGS OR~~ CASTINGS.

I have to report that the undermentioned ~~XXXXX~~ Steel ~~XXXXXXXX~~ castings, manufactured by Messrs. Bergische Stahlindustrie Abt. Loborn of Remscheid for the Vessel No. _____, being built by Messrs. Deutsche Werke A.G. of Kiel have been inspected by me as set forth below and found to be, so far as can be seen, 2 rudder quadrants sound and free from surface defects.--

Forgings or Castings.

Lloyd's
 No. 568/569.
 B.10.10.32.

Düsseldorf 11th October 1932.



	1 rudder quadrant XXXXXXXXXX 568	1 rudder quadrant XXXXXXXXXX 569	STEM.
Material	Annealed Siemens-Martin	Cast Steel	
Condition	cast	cast	
Sound	Yes	Yes	
Condition on Inspection	unmachined	unmachined	
Date Inspected	10.10.32.	10.10.32.	
Standard Test Pieces	.798 3"	.798 3"	
Test—			
Force per square inch	34,7	34,9	
Efficiency per cent.	21,0	20,3	
Fracture Test—			
Time before fracture	120 degr. good	120 degr. good	
Distance from ground	10 feet	10 feet	
Final Test—			
Result according to Rules	satisfactory.	satisfactory.	
Found satisfactory			

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £ _____

To be paid at Düsseldorf.

Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

003727-003733-0052

