

1

"Zamalek"

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME

Steel S.S. "Halcyon"

Report

Jls

No.

41409

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

See Separate Endorsement regarding date of build

100-A-1. Shelter Deck with foreboard

1 Dk (Steel) & Shelter Dk (Steel ws) 2" Dk in No 1 Hold.

All DB 236' 3 5/8", FPT 16", APT 18"

FK, 3 BH to Shelter Dk, 2 BH to upper Dk, Cam, Rhyds A & CP.

B73' on Shelter Dk

Date of build 10.2.1.



© 2021

Jls

21-10-21

Lloyd's Register
Foundation

003742-003749-0159