

F.E.

Ship Surveyor

Received from Chief Ship Surveyor

NAME *Stl & CEDARTREE* Rpt. *Sld* No. *29727*

of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also pointing out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points entered in the endorsement. (Extract from Sub-Committee's Report, 24/5/92.)

Case No. *4425* Depth "d" *15.3 15 U.D.*

Table No. *✓* Description *Bulk angle frames as approved*

Original No. *13336*

Proportions Length *13.53 15 U.D.*  
Depth =

Deck Sheerstrake *as approved*

*Revised Rules*

This vessel appears to have been built in accordance with the approved plans, and it is submitted she is eligible to be classed

- ✱ 100 A.I. (Steel)*
- 1 D<sup>1</sup> (Stl) . Well D<sup>1</sup>*
- Cell D.B. 202' 430t, F.P.T. 127t, A.P.T. 158t.*
- F.K, 4 B.H, Cem, Rlays A CP.*
- Q 147', F 27.*



*[Handwritten signature]*

*[Handwritten signature]*  
*10.5.28.*



© 2020

Lloyd's Register Foundation

005784-003799-0017

*Ld*

*iding*

*or in*

*Any*

*Ap*

*5.*

*8*

*5.*

*8*

*3.*

*8*

*5.*

*2*

*0*

*2*

*15*

*2*

*3.*

*7*

*5*

*2*

*0*

*5.*

*0*

*0*

*9*

*9*

*6*

*6*

*1*

*1*

*14*