

COPY

56231

## LLOYD'S REGISTER OF SHIPPING

Port of Rotterdam.5th June, 1963.

This is to Certify that I have surveyed part of the machinery  
of the **m.s. "WAIRANGI", 12829** Gross tons of Southampton  
for damage to Starboard Main Engine on the 16th May, 1963.

and that all my recommendations have been carried out to my satisfaction. I  
am reporting accordingly and recommending to the Committee of Lloyd's Register  
of Shipping that the machinery classification should be retained and the following  
~~no fresh~~  
~~survey records assigned~~ subject to the special condition at present  
attached to the vessel's class being dealt with as previously  
recommended and also subject to the No.1 lower exhaust gas piston  
yoke of Starboard Main Engine being replaced or machined in way  
of tie rod nut landings before the end of July next.

Parts now examined:—

---

Surveyor to Lloyd's Register of Shipping  
**J. van Son.**

## KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey  
CSM Continuous Survey of Machinery  
DBS Donkey Boiler Survey  
ES Engine Special Survey

MBS Main Boiler Survey  
OF Fitted for oil fuel (date) FP above 150° F.  
SGS Steam Generator Survey  
SPS Steampipe Survey

TS Tailshaft Survey  
TS(CL) Tailshaft Survey—Continuous Liner  
TSN Tailshaft renewed  
TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."