

10,59

4E

class is subject to

the lower cross tube of the donkey boiler being specially examined at the next donkey boiler survey.

16 FEB 1960

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

VESSEL'S NAME..... PANAGHIA..... REPORT..... Nar..... No..... 411.....

The Surveyor reports some damage to after auxiliary oil generator engine and some repairs now effected, and the Surveyor recommends that the class be made subject to the port aft auxiliary generator engine being only used as a standby engine pending repairs and complete overhaul upon the vessels arrival in Greece where she is stated to be proceeding.

IT IS SUBMITTED this vessel is eligible to remain as classed, subject as recommended, and as above.

JW
15.2.60.



© 2020

Lloyd's Register
Foundation

[Handwritten signature]

003824.003831.0079