

1m, 10.33.

2

Head

Sent to Chief Surveyors 18. 9. 34

Received from Chief Surveyors

VESSEL'S NAME

St. Louis TAMAROA

Report

GLS

No. *37931*

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement" — (Extract from Sub-Committee's Report, 24/5/92.)

1st No. *3*

SURVEY

~~PARTLY HELD~~

advanced *Damage & Alterations*

When due

2. 34

When proposed to be completed

within the year of grace

Portion of Survey held, &c.

To complete the survey:— See Report.

NAB

Leakage from S.H.L. - Indented shell plating.



© 2020

Lloyd's Register
Foundation

005867-005874-014