

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Stl Sg "FALCON"*

Report

*Gls*No. *47325*For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/02.)

WRECK
SECTION

No

Nature of Survey

1st Entry

When due

Revised Rules

✠ 100 A. I. (Steel). With freeboard

1 D^k (Stl), 2nd D^k (Stl) in holds.

Cell D.B 176' 220t, F.P.T. 22t, A.P.T. 15t.

F.K, 5 B.H. (3 B.H to weather D^k, 2 B.H to 2nd D^k, Cen, Clydes A/C.P.
B 40'.

© 2020

Lloyd's Register

Foundation

003884-003894-0038

12.27