

003914-003925-0025

The class is subject to the Port Donkey boiler not being used until its safety valves have been placed in order ~~of~~ ^{being} adjusted.

4E

6 JAN 1959

Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME LUISA REPORT Ven No. 0231

SRL: The above item now dealt with.

IT IS SUBMITTED this vessel will be eligible for the record DBS 6.58 when the survey has been completed by examination of ~~its~~ exhaust gas economiser and adjustment of its safety valves, without special condition.

There is no
economiser on this
vessel and the
Palermo Surveyor
(Rpt no. 91) is wrong

6.1.59

Assign DBS 6/58

Q 20/2/59