

Injections 1 sizes 2 Connected to condenser, or to circulating pump YES Is a separate Donkey Suction fitted in Engine

Are the sluices on Engine room bulkhead

S. S. Ophir

No 4.

stated to have been  
returned by Training  
Book.

is submitted the Bilbao Surveyors be requested to  
ward the report on the Boilers of this vessel, which  
are to have been returned to them (Bbo 5572) 21<sup>st</sup> May 19.

A.R.

H.H.G.

27/1/20.

ing Surface of Boilers

Is Forced Draft fitted

✓

No. and Description of Bowers

pressure

Tested by hydraulic pressure to

Date of test

No. of Certi

004003-004008-0147