

adth *wait over*

of keel

FRAMES, DOUBLE

by Chief Ship Surveyor " " Received from Chief Ship Surveyor

'S NAME *Stt T.S. M/V SKOTAAS* Rpt. *Sun* No. *8746*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

*This vessel has left Sundel for Gothenburg to have the machinery installed.*

*It is submitted the Gothenburg Surveyors be advised and requested to give the case the necessary attention and to forward a report on form 8 when the survey has been completed.*

*Stt. Gdt. 15/12/30.*



© 2020

Lloyd's Register Foundation

*S. J.*  
*15/12.30*

004055-004061-0202

Depth and thickness at mid-line in (across section from ... in way of Bridge, Angle, 200

RES IN  
✓  
✓  
✓  
x  
90  
90  
59  
Ac  
53  
150  
64  
90  
✓  
✓  
fla  
spa  
x  
5  
4  
9  
90