

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stt Lw Sc " F. J. WOLFE "* Rpt. *Bmn* No. *1490*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

1st Long^e
Transverse No. *20150*

Depth "d" ✓

Framing: Table No. ✓

Description *Longitudinal framing.*

2nd Longitudinal No. *56550*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *13.42.*

~~Deck~~ Sheerstrake *as approved.*



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✦ *100 A1. (Steel) "Carrying Petroleum in bulk"*
"Web frames", Longitudinal framing.
1 D^k (Stl), 2nd D^k (Stl) clear of cargo tanks, 3rd D^k (Stl) aft of cargo tanks.
Cell DB under E 78' 118t. DTs f 53' 2307t, FPT 295t, APT 249t.
FK 16 BH, pt cem, pt asp, Lloyds' A & CP.
after B 55', B 40', F 39'. Macky aft.
Rudder electrically welded.

[Signature]
© 2020
29. 8. 32
Lloyd's Register Foundation
004076-004083-0179