

FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO ~~AND~~ ^{OR} PASSENGER SHIPS.

When received in London Office

24 FEB 1933

Port CopenhagenName S/S ALEXANDRAOfficial No. ✓No. in Reg. Book 56807Port of Registry (For Foreign Ships) EsbjergIron or Steel Steel State whether Classed by Lloyd's Register yesName of Owners Det Forenede Dampskibs Selskab Date of Verification 12th February 1933

I have to report that the Freeboards as given below, assigned by the DANISH AUTHORITIES Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:—

FREEBOARD AMIDSHIPS FROM TOP OF DECK LINE, WOOD/ STEEL DECK.	FROM CENTRE OF DISC.
Tropical Fresh Water <u>✓</u> ft. <u>✓</u> ins.	<u>✓</u> ins. above
Fresh Water <u>648</u> <u>7/4</u> ins.	<u>114</u> <u>3/4</u> ins. above <u>4 1/2</u>
Tropical <u>✓</u> ft. <u>✓</u> ins.	<u>✓</u> ins. above
Summer <u>2-6"</u> <u>762</u> <u>3/4</u> ins.	
Winter <u>826</u> <u>7/4</u> ins.	<u>64</u> <u>7/4</u> ins. below <u>2 1/2</u>
Winter North Atlantic <u>✓</u> ft. <u>✓</u> ins.	<u>✓</u> ins. below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:— 17'-3 3/4"

S. Clausen Surveyor.

(To be filled up in London Office.)

Statement No. _____ Date of Committee's Minute 27. 2. 33

Particulars for Record in Register Book.	Moulded Depth	<u>19</u> ft. <u>6</u> ins. <u>✓</u>
	Freeboard	<u>2</u> ft. <u>6</u> ins. <u>✓</u>
	Corresponding Draught	<u>17</u> ft. <u>3 3/4</u> ins. <u>✓</u>

Freeboards compared and found correct by AMB Date 25/2/33Is fee paid? _____ Form for Certificate Daniel

Instructions _____ Date _____

Certificate written by Daniel Clausen Noted for posting yes