

Ship Surveyor _____

Received from Chief Ship Surveyor _____

IME Steel S.S. "WANDLE" Rpt. Lth. No. 18282

is of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

by _____

This vessel has left Leith for Sunderland to have the machinery installed.


It is submitted the Sunderland Surveyors be requested to give the case the necessary attention and to forward a report on Form Rpt.8 when the survey has been completed.

[Handwritten signature]

[Handwritten signature]
11.10.32

Leith Surveyors should be requested to forward particulars of test the steel wire supplied.

me
letto



© 2020

Lloyd's Register Foundation

It is concluded the thickness of the bridge deck plating is as proved, but the Surveyors should be requested to state if this is so.

11/6/32

004230-004237-0121

004230-004237-0122