

NAB

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, Fen, London

Telephone: ROYal 9166

4th February, 1959.

## Enclosures

Dear Sirs,

### S.S. "WAVE CONQUEROR"

With reference to your cablegram of the 31st January and mine of the 2nd February, I enclose herewith photostat copies of Southampton Report No.23406 and Newcastle Report No.114144 dealing with the main engine gear wheel and pinions. I think it well to add that when the main engine gear wheel and pinions were last examined at Curacao in September 1957 they were found in a satisfactory condition.

The Survey position is as follows :-

Special Survey due 1.61.  
Main Boiler Survey due 2.58.  
Donkey Boiler Survey due 2.58.  
Screwshaft Survey due 11.58.  
Steampipe Survey due 2.63.  
Last seen in dry dock 1.57

There are no conditions of class attached to this ship other than that relating to the gear wheel etc.

Yours faithfully,

Clerk to the  
Classification Committee.

L.S. Sims Esq.,  
HAVRE.



© 2020

Lloyd's Register  
Foundation

004275-004284-0227