

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel Raddle S. "Gordon"* Rpt. *Low.* No. *11464.*



The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *57.5*Depth "d" *6.42'*Framing: Table No. *3*Description *angle bar frame as*Longitudinal No. *8832**approved.*Proportions Length = *22.8*
Depth =

~~Deck~~ Sheerstrake *and other scantlings as approved*
for vessels of the "A" class.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *A.1. (Steel) "For Woolwich Ferry Purposes."*
18k (pt. Stl)

FK, 7BH, Asp, Lloyd's A. & C.P.

© 2020

Lloyd's Register Foundation

004338-004350-0097