

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Steel S.S. "SOLANA" Report RL No. 4142**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

✱ 100 A-1. (Steel) "Carping petroleum in bulk"  
 2 Dks (Steel) & Rib frames - longitudinal framing.  
 All IB & E & B 65' 2 1/2" t, FPT 29 1/4" t, APT 46" t  
 FK, 14 BH (9 to Upper Dk, 5 to 2nd Dk) pt Cen, Av CP, P101' B36' F34'  
 No chy Aft



© 2021

 Lloyd's Register  
 Foundation

004358-004363-0146