

REPORT ON ELECTRICAL EQUIPMENT.

(OTHER THAN FOR THE PROPULSION OF THE VESSEL)

DEC 16 1940

Received at London Office.....

Date of writing Report 4th Dec. 40 When handed in at Local Office.....19..... Port of Hartlepool

No. in Survey held at West Hartlepool Date, First Survey 18th Sept Last Survey 4th Dec, 1940
Reg. Book. Supp. (Number of Visits.....9.....)

28511 on the S.S. "13 MAILA" Tons { Gross 6793.06
Net 3969.29

Built at West Hartlepool By whom built Tom. Swan & Co. Ltd Yard No. 1105 When built 1940

Owners British India Steam Navigation Co. Ltd Port belonging to London

Electrical Installation fitted by The Sunderland Eng. Co. Ltd Contract No. 1105 When fitted 1940

Is vessel fitted for carrying Petroleum in bulk no Is vessel equipped with D.F. Yes E.S.D. no Gy.C. no Sub.Sig. no

Have plans been submitted and approved Yes System of Distribution house wire Voltage of supply for Lighting 110

Heating 110 Power 110 Direct no Alternating Current, Lighting Yes Power Yes If Alternating Current state frequency..... Prime Movers,

has the governing been tested and found efficient when the whole load is suddenly thrown on and off Yes Are turbine emergency governors fitted with a

trip switch as per Rule..... Generators, are they compound wound Yes, are they level compounded under working conditions Yes,

if not compound wound state distance between generators..... and from switchboard..... Where more than one generator is fitted are they

arranged to run in parallel no, are shunt field regulators provided Yes Is the compound winding connected to the negative or positive pole

Positive Have machines over 100 kw. been inspected by the Surveyors during manufacture and testing..... Have certificates of

test for machines under 100 kw. been supplied Yes and the results found as per rule Yes Are the lubricating arrangements and the construction

of the generators as per rule Yes Position of Generators Engine room starboard side aft

is the ventilation in way of generators satisfactory Yes are they clear of inflammable material Yes, if situated

near unprotected combustible material state distance from same horizontally..... and vertically..... are the generators protected from mechanical

injury and damage from water, steam and oil Yes, are the bedplates and frames earthed Yes and the prime movers and generators in metallic

contact Yes Switchboards, where are main switchboards placed Engine room starboard side on

raised platform near engine room star

are they in accessible positions, free from inflammable gases and acid fumes Yes, are they protected from mechanical injury and damage from water, steam

and oil Yes, if situated near unprotected combustible material state distance from same horizontally..... and vertically....., what insulation

material is used for the panels Slate, if of synthetic insulating material is it an Approved Type....., if of

semi-insulating material (slate or marble) are all conducting parts insulated therefrom as per Rule Yes Is the frame effectually earthed Yes

Is the construction as per Rule Yes, including accessibility of parts....., absence of fuses on the back of the board Yes, individual fuses

to pilot and earth lamps, voltmeters, etc., Yes locking of screws and nuts Yes, labelling of apparatus and fuses Yes, fuses on the "dead"

side of switches Yes Description of Main Switchgear for each generator and arrangement of equaliser switches House pole

knife switch and house pole fuse


and for each outgoing circuit Single pole three way knife switch and house

pole fuse

Are compartments containing switchboards composed of fire-resisting material or lined as per Rule Yes Instruments on main switchboard Three

ammeters Three voltmeters..... synchronising devices. For compound machines in parallel is the ammeter connected on the pole opposite to the

equaliser connection..... Earth Testing, state means provided Elamps connected to E. then from each fuse



Switches, Circuit Breakers and Fuses, are they as per Rule 7/2, are the fuses an approved type 7/2, are all fuses labelled as per Rule 7/2, are the reversed current protection devices connected on the pole opposite to the equaliser connection 7/2, have they been tested under working conditions 7/2. Joint Boxes, Section Boards and Distribution Boards, is the construction and position as per Rule 7/2. Cables, are they insulated and protected as per the appropriate Tables of the Rules 7/2, if otherwise than as per Rule are they of an approved type 7/2, state maximum fall of pressure between bus bars and any point under maximum load 5.307 are the ends of all cables having a sectional area of 0.04 square inch and above provided with soldering sockets 7/2. Are paper insulated and varnished cambric insulated cables sealed at the exposed ends 7/2 with insulating compound 7/2 or waterproof insulating tape 7/2. Are all the cable runs in accessible positions, not exposed to drip or accumulation of water or oil, high temperatures or risk of mechanical damage 7/2, are cables laid under machines or floorplates 7/2, if so, are they adequately protected 7/2. Are cables in machinery spaces, galleys, laundries, etc., lead covered 7/2 and H.R.B. 7/2. State how the cables are supported and protected 7/2. L.C.B. and H.R.B. cables clipped to surface in engine rooms 7/2. H.R.B. cables run in galv. pipe or deck alongside hatch coaming 7/2. L.C.B. cable clipped to wood grinders or to surface in access 7/2. Are all lead sheaths, armoring and conduits effectually bonded and earthed 7/2. Refrigerated chambers, are the cables and fittings as per Rule 7/2. Are all cables passing through decks and watertight bulkheads provided with deck tubes or watertight glands 7/2, where unarmoured cables pass through beams, etc., are the holes effectually bushed 7/2 and with what material Lead or fibre. Alternative Lighting, are the groups of lights in the engine and boiler rooms arranged as per Rule 7/2. Emergency Supply, state position 7/2 and method of control 7/2. Navigation Lamps, are they separately wired 7/2 controlled by separate double pole switches 7/2 and fuses 7/2. Are the switches and fuses in a position accessible only to the officers on watch 7/2, is an automatic indicator fitted 7/2. Secondary Batteries, are they constructed and fitted as per Rule 7/2, are they adequately ventilated 7/2. Fittings, are all fittings on weather decks, in stokeholds and engine rooms and wherever exposed to drip or condensed moisture, weatherproof 7/2. Are fittings installed where readily combustible materials or inflammable or explosive dust or gases are likely to be present 7/2, if so, how are they protected 7/2. and where are the controlling switches fitted 7/2, are all fittings suitably ventilated 7/2. are all fittings and accessories constructed and installed as per Rule 7/2. Searchlight Lamps, No. of 7/2, whether fixed or portable 7/2, are their fittings as per Rule 7/2. Heating and Cooking, is the general construction as per Rule 7/2, are the frames effectually earthed 7/2, are heaters in the accommodation of the convection type 7/2. Motors, are all motors constructed and installed as per Rule 7/2 and placed in well-ventilated compartments in which inflammable gases cannot accumulate and free from damage from water, steam and oil 7/2, if situated near unprotected combustible material state minimum distance from same horizontally 7/2 and vertically 7/2. Have motors of 100 BHP and over been inspected by the Surveyors during manufacture and testing 7/2. Have certificates of test for motors under 100 BHP intended for essential services been supplied and the results found as per Rule 7/2. Control Gear and Resistances, are they constructed and fitted as per Rule 7/2. Lightning Conductors, where required are they fitted as per Rule 7/2. Ships carrying Oil having a Flash Point less than 150° F. Have all the special requirements of the Rules for such ships been complied with 7/2, are all fuses of the cartridge type 7/2 are they of an approved type 7/2. If portable lamps for use in dangerous spaces are supplied, are they of a self-contained battery-fed flameproof type 7/2. Spare Gear, if the vessel is for open sea service have spares been provided as per Rule 7/2, are they suitably stored in dry situations 7/2. Insulation Tests, has the insulation resistance of all circuits and apparatus been megger tested and found satisfactory 7/2.

PARTICULARS OF GENERATING PLANT.

DESCRIPTION OF GENERATOR.	No. of	RATED AT				DRIVEN BY	WHERE DRIVEN BY AN INTERNAL COMBUSTION ENGINE.	
		Kilowatts.	Volts.	Amps.	Revs. per Min.		Fuel Used.	Flash Point of Fuel.
MAIN	3	30	110	273	685	Single exp. steam engine		
EMERGENCY								
ROTARY TRANSFORMER								

GENERATOR CABLES.

DESCRIPTION.	KILOWATTS.	CONDUCTORS.		MAXIMUM CURRENT IN AMPERES.		APPROX. LENGTH (lead plus return feet).	INSULATED WITH.	HOW PROTECTED.
		No. in Parallel Per Pole.	Sectional Area or No. and Dia. of Strands. Sq. ins. or sq. mm.	In the Circuit.	Rule.			
MAIN GENERATORS	3 x 30	1	37/082	273	296	48	V.C.	L.C.B.
" " EQUALISER						40		
						36		
EMERGENCY GENERATOR								
ROTARY TRANSFORMER: MOTOR								
" " GENERATOR								

MAIN DISTRIBUTION CABLES.

DESCRIPTION.	KILOWATTS.	CONDUCTORS.	MAXIMUM CURRENT IN AMPERES.	APPROX. LENGTH (lead plus return feet).	INSULATED WITH.	HOW PROTECTED.
AUX. SWITCHBOARDS AND SECTION BOARDS						
Officers' Htg. Section Board feed:-	2	19/064	160	166	192	V.I.R. H.R.B.
Engine Room Htg. Section Board feed:-	2	19/064	150	166	72	V.I.R. H.R.B.
Officers' Htg. Section Board feed:-	1	7/064	28	46	192	V.I.R. H.R.B.
Officers' Htg. Section Board feed:-	1	7/064	23	46	72	V.I.R. H.R.B.
Engine Room Htg. Section Board feed:-	1	19/064	47	83	72	V.I.R. H.R.B.
Engine Room Htg. Section Board feed:-	1	7/064	35	46	192	V.I.R. H.R.B.
Engine Room Htg. Section Board feed:-	1	7/064	37	46	60	V.I.R. H.R.B.
Engine Room Htg. Section Board feed:-	1	7/064	*	46	60	V.I.R. H.R.B.

LIGHTING AND HEATING, ETC., CABLES.

DESCRIPTION.	KILOWATTS.	CONDUCTORS.	MAXIMUM CURRENT IN AMPERES.	APPROX. LENGTH (lead plus return feet).	INSULATED WITH.	HOW PROTECTED.
WIRELESS		1	7/064	20	31	382 V.I.R. H.R.B. & L.C.B.
NAVIGATION LIGHTS		1	7/064	13	46	382 V.I.R. H.R.B. & L.C.B.
LIGHTING AND HEATING		1	7/064	19	46	432 V.I.R. H.R.B.
Off Htg. D.B.		1	19/064	43.6/52	83	6,607.5 V.I.R. L.C.B.
3 D.B. Htg. Htg. S.B.		1	19/064	82.68	83	15.84 V.I.R. L.C.B.
2 D.B. Htg. Htg. S.B.		1	7/036	10,6/12	24	6,607.5 V.I.R. L.C.B.
3 D.B. Htg. Htg. S.B.		1	7/036	11/12	24	15.84 V.I.R. L.C.B.
2 D.B. Htg. Htg. S.B.		1	7/064	27.20	46	120/15 V.I.R. H.R.B. & L.C.B.
2 D.B. Htg. Htg. S.B.		1	7/064	30	46	8 V.I.R. H.R.B.
Engine Room Htg. D.B. Htg. E.R.S.B.		1	7/064			

MOTOR CABLES.

ALL IMPORTANT MOTORS TO BE ENUMERATED.	No.	B.H.P.	CONDUCTORS.	MAXIMUM CURRENT IN AMPERES.	APPROX. LENGTH (lead plus return feet).	INSULATED WITH.	HOW PROTECTED.
Engine Room Vent. Fans	3	2	1	7/064	18	31	20,60/42 V.I.R. H.R.B.
Oil Separator	1	0.5	1	7/064	4.75	31	45 V.I.R. H.R.B.
Refrig. Htg. S.B.	1	3	1	7/064	25	31	28 V.I.R. H.R.B.
Refrig. Htg. S.B.	1	1	1	3/036	9	12	22 V.I.R. H.R.B.
Pump	1	60 watt	1	3/029	0.5	7.8	120 V.I.R. H.R.B.
Fan	1	0.75	1	7/029	7	18.2	130 V.I.R. L.C.B. & A.B.
Deck Cleaning Motor	*		1	7/064		31	V.I.R. L.C.B. & A.B.
Drill & Htg. Workshop S.B.	*		1	7/064		31	V.I.R. L.C.B. & A.B.

Note: Circuits wired for drill and lathe motors to be fitted at future date

The Electrical Equipment is installed in accordance with the approved plans and the requirements of the Rules.
 All Insulated Conductors are guaranteed to have been tested at the maker's works as specified in the Rules.
 The foregoing is a correct description.

H. W. Sunderland *Lodge* *by* *H. W. Sunderland* Electrical Engineers. Date *5. 12. 1940.*

COMPASSES.

Minimum distance between electric generators or motors and standard compass *112 feet*

Minimum distance between electric generators or motors and steering compass *106 feet*

The nearest cables to the compasses are as follows:—

A cable carrying *14* Ampères *on the* feet from standard compass *7* feet from steering compass.

A cable carrying *14* Ampères *7* feet from standard compass *on the* feet from steering compass.

A cable carrying Ampères feet from standard compass feet from steering compass.

Have the compasses been adjusted with and without the electric installation at work at full power *Yes*

Has the effect of switching on and off circuits, motors and other electro-magnetic apparatus within the vicinity of the compasses been noted *Yes*

The maximum deviation due to electric currents was found to be *Nil* degrees on *Every* course in the case of the standard compass, and *Nil* degrees on *Every* course in the case of the steering compass.

L. S. Simpson Builder's Signature. Date *7. 12. 1940.*

Is this installation a duplicate of a previous case *Yes* If so, state name of vessel *"Stora"*

General Remarks (State quality of workmanship, whether insulation tests, etc., have been made, opinions as to class, etc.) *The electrical*

equipment of this vessel has been fitted out under special survey and in accordance with the approved plans. The materials used are of good quality and the workmanship is good. On completion the equipment was run under working conditions with satisfactory results, the governing, regulation and compounding of the generating sets were tested and the insulation resistance of all circuits was measured and found good. This equipment is in my opinion suitable for a classed vessel.

Noted
17/12/40

Total Capacity of Generators *90* Kilowatts.

The amount of Fee ... £ *31 : 10* : When applied for,

Travelling Expenses (if any) £ : : When received, *11 Jan. 1941*

Simpson
Surveyor to Lloyd's Register of Shipping.

Committee's Minute

FRI. 20 DEC 1940

Assigned

See Hpl F.C. 18096

Transfer. (MADE IN ENGLAND.)
(The Surveyors are requested not to write on or below the space for Committee's Minutes.)



© 2021

Lloyd's Register Foundation