

VRG

REPORT on the "DON GEDDIK" ex "Duyfduyk."

It is submitted the Rotterdam Surveyors be requested to
 that the displacement of 22983 cubic metres is at 85% of ρ_{sw} (shoulded
 $T=10.363m$) verify the height of Bridge between decks & give the Freeboard
 over above (or below) a line drawn parallel to the keel through the sheer line
 ships.

They should also report the scantlings of the Machinery casings within
 ridge between decks with means of closing any openings in it, &
 the closing appliances provided for the air pipes, & details also of the
 and escape companionway in the poop between decks.

The Surveyors should also be requested to forward
 in amended copies of the appropriate Machinery Section
 and Profile and decks as required by
 Para 4 of Instructions

Return plans
 memoranda

to Surveyors

© 2020

Lloyd's Register
 Foundation

5410-745400-145400

8410-745400

Nils ML