

6,500,10,40.

the form... should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case

BC

26 JUN 1950

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

GB  
VESSEL'S NAME 'G L E N E L G' REPORT Mtl No. 8114

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

This vessel is classed BS (Great Lakes & River St. Lawrence Service).

The MONTREAL Surveyors report (3.50), the vessel afloat, the requirements of the Lake S.S. due 4.49 complied with.

Tank top plating corrugated but in order.

IT IS SUBMITTED the vessel is eligible to remain as classed by the British Corporation, and to have the Notations of 'Lake S.S. 3.50' and 'Annual Survey 3.50' assigned as recommended.

BS (Great Lakes & River St. Lawrence Service)  
Lake S.S. 3.50  
Annual Survey 3.50

ENDORSEMENT OF CLASS (B).

Tank top plating corrugated



© 2020

Lloyd's Register  
Foundation

*Handwritten signature*  
32650

004591-004595-0098

Stringers .....	Have Ventilators and their Coamings been examined and found efficient? <b>Yes</b>	Timbers of Frame at openings .....	Chain Locker .....
Inner Bottom Plating <b>Corrugated but in</b>		" " at other places .....	Hangers & W...