

F.E.

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

EL'S NAME *Sto Se K. GYLLIR*

Rpt. *Bonn*

No. *828a*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long
Transverse No. *2225*

Depth "d" *11.85*

Framing: Table No. *1*

Description *Bull angle frames as approved*

1st Longitudinal No. *5990*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *9.9*

Deck Sheerstrake *as approved*

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A.1. (Steel) "Steam Trawler"

1 D^K


Cell D.B. 29' 36t, F.P.T. 8t, A.P.T. 13t.

B.K 7³/₈, H.B.H, Cem, Lloyds A.C.P.

F. 24'



for 23/7/26



© 2020

Sil 22.2.26

The Surveyor should be requested to forward the forging reports as these do not appear to have been received with their report.

Lloyd's Register Foundation

004621-004629-0219