

M.S. ....

"PORT WYNDHAM"

According to the records in this office, the following remains to complete the Continuous Survey Cycle of the machinery at this date. It should be borne in mind that delay in completing the Survey may involve the examination of additional items. *Items have not been seen for 4 years or more.*

Port main engine : - No 3 cylinder, pistons & rods, valves & gears  
~~side crankpins & bearings.~~ *EXC.*

Starbd main engine : - No. 1 side connecting rods, top ends & guides  
No. 1 centre crankpin and bearing.  
No. 3 side crankpins and bearings.  
Scavenge pump.

Auxiliaries : - Port independent L.O. pump.  
Aft boiler feed pump.

Starbd outbd. and steam driven air compressors, coolers  
& relief devices.

Two aux. air receivers & relief devices (not port fwd).

SPS should be held.

X Before issuing this list the New York Surveyors should be referred to their Report No. 62466 of October, 1963 and Interim Certificate; the Report states No. 4 port side crankpins examined and the Interim Certificate states No. 3 port side crankpins examined. They should be asked to state which is correct and the above list then amended if necessary X

© 2020  
Lloyd's Register  
Foundation