

REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship "FORT CARIBOU" Official Number 168485 Port of Registry LONDON.

Place of Survey TARANTO, ITALY Date of Survey 1<sup>st</sup> Dec 1944 Date of last Load Line Survey issued 12<sup>th</sup> July 1943  
in force 31<sup>st</sup> May 1948




ISSUED BY THE BOARD OF TRADE.

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>HATCHWAYS INCLUDING SMALL HATCHWAYS.</b>			
<b>1. Exposed on freeboard deck.</b>			
Coamings, their stays and stiffeners ...	Good ✓		
Beams ...	- do - ✓		
Fore and afters ...	nil ✓		
*Covers ...	Good ✓		
*Tarpaulins (State number per hatchway)	- do - (3) ✓		
*Cleats and battens ...	- do - ✓		
Lashings and their fittings ...	- do - ✓		
Wedges ... (Is supply, including spares, adequate?)	- do - yes ✓		
<b>2. Exposed on superstructure decks, including raised quarter decks. CASING TOP TO BUNKERS.</b>			
Coamings, their stays and stiffeners ...	Good ✓		
Beams ...	nil ✓		
Fore and afters ...	nil ✓		
*Covers ...	Good ✓		
*Tarpaulins (State number per hatchway)	- do - (2) ✓		
*Cleats and battens ...	- do - ✓		
Lashings and their fittings ...	- do - ✓		
Wedges ... (Is supply, including spares, adequate?)	- do - yes ✓		
<b>3. Within superstructures not intact or not protected by Class I closing appliances.</b>			
Coamings...	/		
Beams ...			
Fore and afters ...			
Covers ...			
Tarpaulins (State number per hatchway)			
Cleats and Battens ...			
Wedges ... (Is supply, including spares, adequate?)			

\* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).



Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
<b>VENTILATORS IN EXPOSED POSITIONS.</b>			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections ... ..	<i>Good ✓</i>		
Closing arrangements ... ..	<i>- do - ✓</i>		
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections ... ..	<i>Good ✓</i>		
Closing arrangements ... ..	<i>- do - ✓</i>		
<b>AIR PIPES.</b>			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements ... ..	<i>Good ✓</i>		
7. Within partially enclosed superstructures.			
Closing arrangements ... ..	<i>✓</i>		
<b>MACHINERY CASINGS.</b>			
8. Casing Top.			
Fiddle openings, their covers and fastenings ... ..	<i>Good ✓</i>		
Skylights, their fastenings, covers and lashings ... ..	<i>- do - ✓</i>		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings ... ..	<i>Good ✓</i>		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings ... ..	<i>✓</i>		
11. Within partially enclosed superstructures.			
Doors and fastenings ... ..	<i>✓</i>		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	<i>✓</i>		
13. COMPANIONWAYS including deckhouses enclosing ladderways.			
Doors, fastenings, covers ... ..	<i>Good ✓</i>		

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle ... ..	<i>✓</i>		
Bridge, fore end... ..	<i>✓</i>		
Bridge, after end ... ..	<i>✓</i>		
Poop ... ..	<i>✓</i>		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures ... ..	<i>✓</i>		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves ... ..	<i>Good ✓</i>		
17. SIDE SCUTTLES AND DEADLIGHTS.			
18. GUARD RAILS			
	<i>Good ✓</i>		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways ... ..	<i>✓</i>		
20. LIFELINES (fittings and material)			
	<i>Good ✓</i>		
21. FREEING PORTS.			
Shutters ... ..	<i>✓</i>		
Protection bars ... ..	<i>Good ✓</i>		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances ... ..	<i>✓</i>		
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	<i>✓</i>		
24. LOAD LINE MARKS			
	<i>Verified and found correct.</i>		

Particulars of any change from the conditions given on the Load Line Certificate or on Form L.L.4.D.

NONE.

**Certificate A. To be signed by Surveyor in respect of a partial or complete survey.**

I have surveyed the ship named at the head hereof, to the extent indicated below, and in accordance with the instructions contained in Board of Trade Circular 1687 and the requisite details of the survey have been entered herein.

Index Nos. of items examined.†	Signature of Surveyor.	Place.	Date.
All.	A. S. Fletcher.	Taranto Italy	1 <sup>st</sup> December 1944

**Certificate B. To be signed by Surveyor completing the survey.**

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor A. S. Fletcher. Place Taranto Italy Date 1<sup>st</sup> December 1944.

The Survey was not\* carried out concurrently with the survey for Passenger Certificate.

Signature A. S. Fletcher.

Date 4<sup>th</sup> December 1944.

NO JAN 1945  
A.S.

† Insert "all" in case of a complete survey.  
\* Delete this word if inapplicable.

NO FEE CHARGED AT THIS PORT.

Forwarded for Owners & Classification Society.  
Spaldale.  
M.W.T.S.-MED.  
SURVEY.  
M.W.T.  
S.R. DIV<sup>n</sup>.

A/c rendered from  
London 2 FEB '45



© 2021

Lloyd's Register  
Foundation