

2 MAR 1964

Ship's name m/v "GLOUCESTER" Port YKA 5085.
AUK No. 11319.

Last survey date

Class is subject to:-

M.B.

- (1) Repairs to Main Engine No. 4 unit "A" frame, diaphragm plate and crankcase being specially examined by 6/64.
- (2) Repairs to the water jacket, bedplate and crankcase in way of No. 6 unit of Starboard Forward Generator Engine being specially examined by 6/64.

Damage stated sustained by Port Aft Generator Engine due to breakage of a bottom end bolt.

Before this case receives consideration,
Submitted Kobe Surveyors be cabled as follows:-

"GLOUCESTER CABLE WHETHER PORT AFT GENERATOR
ENGINE REPAIRS SURVEYED YOUR PORT RECENTLY
STOP IF SO FORWARD REPORT URGENTLY".

✓-13

End

2.3.64.

Cable 2.3.64



© 2020

Lloyd's Register
Foundation

004653-004661-0216