

The condition of the following items is to be described as 'good' only when the part has been examined until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the next examination, the condition should be described as 'not good' and the defects and repairs should be described. The condition of machinery should be described as 'not good' only when the defects and repairs should be described. The condition of machinery should be described as 'not good' only when the defects and repairs should be described.

The class is subject to the donkey boiler furnaces being specially examined at the next DBS and to the auxiliary condenser inlet water box being renewed by 5.60.

23 OCT 1959 4E

Received from Chief Engineer Surveyor.....

by Chief Engineer Surveyor.....

NAME SAMEIRO REPORT Lis. No. 8413

CS advanced.

DBS due 1.59 part held 5.59 now completed.

SRL: The starboard donkey boiler furnaces now specially examined and gauged and found to remain efficient.

The Surveyor recommends that the subject of class be continued.

IT IS SUBMITTED that this vessel is eligible to remain as CLASSED, with fresh record DBS 5.59 now as previously recommended, subject as above.

22.10.59.

RB to note

Machinery numeral (1015) in Appendix to RB as now.
SHP is 4400 ie. MN = 880



© 2020

Lloyd's Register Foundation

004718-004726-0198

DBS 5.59