

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Steel S. Motor Vessel "POLLO"*

Rpt. *Sea*

No. *11066*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. *37.75*

Depth "d" *11-12*

Framing: Table No. _____

Description *Single angle*

Longitudinal No. *4719*

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.2$

~~Deck~~ Sheerstrake and other Slantings as approved for
to A.1. Class

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

** A.1. (Steel) For River and Harbour purposes only*

Carrying oil fuel in bulk. F.P. above 150°F

1 Dk (Steel)

FK, 7BH, ft Cen, Plus No A.C.P. Machinery Off

M

TH

2-11-21



© 2020

Lloyd's Register Foundation

004727-004735-0003