

12. JUL 1965

Ship's Name ~~SS~~/MS "SANTA MAFALDA"
 R.B. 31915
 Gross tons 1220 Port of Registry AVEIRO Port Lisbon
 Date of build 8-1948 Is there a Rpt. 9? No Rpt. No. 11116
 No. of visits Two First date 9th June, 1965 Last date 11th June, 1965
 Interim Cert. issued & copy herewith? Yes Damage rpt. issued & copy herewith? No Last rpt. (H.Q. only) *See 10886*
 Date of completing rpt. 7th July, 1965 Surveyed at, if different from Port above -
 Surveyed afloat and/or in D.D. Drydock Last date of examination in D.D. 11th June, 1965
 Has a Load Line Survey been held? - Summer freeboard as verified -

State which additional Rpt. 8 is attached: ~~Good~~ (PS); ~~DR~~; ~~EC~~; ~~Re~~

Survey fees
 D.S. & Repairs
 Esc:- 1,200\$00

Damage fee -

Expenses Esc:- 80\$00

S.A. fee -

I have surveyed the above-named ship in accordance with the Rules for Docking Survey

Wear and Tear Repairs - Abreast aft gallow sheer strake and abaft forward gallow E & F strakes 8 frame spaces length of each strakes was renewed on account of wire and trawl board damage at Owners' initiative. Examined on completion and hose tested and found in order.

Machinery Reports Department - Propeller (VP) and fastenings examined and found in order. Guard not removed.

Noted Jh 28/7/65

ENG JUN

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated. I recommend, therefore, that this ship remain as classed with/ ~~without~~ fresh record of dry docking D.S. 6,65

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee TUESDAY - 3 AUG 1965

Minute

DS 6.65

For H. Nairn
 Surveyor to Lloyd's Register of Shipping
 Jas. H. Nairn

Lloyd's Register
 Foundation

FOR CHAIRMAN
 CLASSN. CITE

004799-004809-006471

ALSO FOR

SPL FOR

TRQ

CORDE

SRL

POSTING

HEADER

CERT

action taken or recommended should be described fully under "defects & repairs". When any part has been subjected to pressure test this should be stated.

date of the next Special Survey. Where repairs have been effected or it is considered that re-examination or repairs should be made before that date the circumstances and

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition and is considered to be acceptable until the due

Rpt. 8 (P.S.) DRY CARGO SHIP

Ship's Name ~~SS~~MS "SANTA MAFALDA"

Port Lisbon

S.S. (5,64) Due 5,68

Rpt. No. 11116

In dry dock from 9th June, 1965

In dry dock to 11th June, 1965

Examined & conditionExamined & condition

Shell plating Good

Sternframe Good

Rudder Good

Was rudder lifted? No

Plating, etc. in way
of shell openings GoodSide scuttles
& deadlights GoodOverbd. scuppers
& discharges Good

F.P. spaces N.E.

Chain locker N.E.

A.P. spaces N.E.

Engine space N.E.

Boiler space -

Under E. & B. N.E.

Coal bunker -

Tunnel & well -

Cement, asphalt,
etc., on btm. shell N.E.

Weather decks Good

* Casings Good

* Deckhouses Good

* Superstructures Good

* Skylights Good

* Companionways Good

* Hatchways Good

* Ventilators Good

Other items: -

* Air & sounding pipes Good - On deck

Doubblers under " " -

Steering arrangements (main) Good

" " (aux) Good

Windlass Good

Masts & standing rigging Good

Hand pumps & suction -

W.T. doors -

Bulwarks, freeing ports, etc. Good

EQUIPMENT:

Equipment letter f †

Fee ltr., if diff. from eqpt. ltr. -

Anchors: No. on board 3 B 1 S

State if ranged No

Length on board -

Cables { Mean dias. range from - to -
Rule length - Dia. -

Mooring ropes Good

* These items to include their closing appliances

Where a part Special Survey and, say, Dry Docking Survey are held at
the same time, the items for SS should be marked "For SS"

© 2020

Surveyor to Lloyd's Register of Shipping
Jas. H. Nairn

004799-004809-0064 2/2