

5m, 9, 35.

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel Twin Sc. "CITY OF CAPE TOWN" Report Liv. No 109742**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER OFFICER.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey FIRST ENTRY When due _____

100A1 "With Freeboard"
"Carrying Cargo oil F.P. above 150^OF in Deep Tank"

2 Dks. 3rd Dk. in No.1 hold.

Cell.DB 422' 1947t, DTa 30' 721t, Tanks in way of tunnels 192t,
FPT 88t, APT 82t.

FK., duct keel forward of machy. space, 172', 8BH, pt.cem., Lloyd's A & CP.

P 76', B & F 351'

O.L.515.5'.

*Yes. See letter
30/10/37.*

*It is submitted the Surveyors are requested to state if
the solid floor and supports are shown or shown in the drawings
Plan or as shown in the report at 5' apart.*

28/10/37

2020

*Lloyd's Register
Foundation*