

0104 2 1/2

See Paid

Received from Chief Surveyors

Chief Surveyors

Grk. No. 20579

EL'S NAME Sc. M.V. "DAVILA"

Report

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

When due

1st Entry

100A1 "Carrying petroleum in bulk"
1 Dk., 2nd Dk. clear of cargo tanks, Longitudinal framing at bottom and at deck.

Cell. DB ^{UE} 69' 162t, DTr 25' 281t, FPT 143t, APT 94t.

FK, 17BH., ~~pt. com.~~, Lloyd's A & CP.


P 90', B 42', F 69'.

Machy. aft.

O.L.484'.



10/6/38



© 2020

Lloyd's Register
Foundation

004900-004905-0104 1/2