

004918 - 004926 - 0194

Ship's name JOHN HOLT

Port BRW.

No. 4163

Last survey date 29-7-63

Class is subject to: NIL

MBS due 8/63, now commenced.

The ES become due 5/62 and was completed at Liverpool and the notation ES 8/62 assigned.

The Surveyor reports

1. Exhaust turbine rotor bearings wiped.
2. A number of air heater tubes in both P+S main boilers wanted.

The Owners requested the repairs be deferred until the ship arrival at a Liverpool port now proceeding and the Surveyor recommends the turbine rotor bearings be re-metalled and air heater tubes in both P+S main boilers be specially examined and dealt with as necessary on ships arrival at Liverpool where now proceeding.

The BRW Surveyor report a part examination for advancement of ES notation in accordance with Circular No. 2151 has been complied with.

It is submitted that this

vessel is eligible for

RECORD. ES (Adv) 7/63 and MBS 7/63, when the surveys have been completed and subject above as recommended.

To complete MBS: P+S boiler safety valves be adjusted and subject item

End. E.2

To complete ES (Adv) Pumping arrangement be tested.



© 2020

19-9-63

Lloyd's Register
Foundation