

WRECK  
SECTION

Received from Chief Ship Surveyor 23 JAN 1957

SHIP'S NAME "MIRZA" No. 825C REPORT Yka. No. 2108

GB

Outstanding Conditions of Class:

Subject to the shell plating in way of Nos. 3 & 4 wing tanks (s.s.) and Nos. 5, 6 & 7 wing tanks (p & s) also in way of A.P. tank being specially examined for leakage on discharge of present cargo by 12,56.

Endorsement of Class (B) (~~As before~~ or None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Wear and tear repairs to part of the deferred items as above:  
Temporary repairs to fractured shell plate J.1 (s.s. from aft).

Recommendation:

SUBJECT to shell plate J.1 (s.s. from aft) being renewed next Special Survey, and to 15 fathoms of chain cable being supplied at the earliest opportunity, but without other condition.

As Now. Subject  
Without.



© 2021

Lloyd's Register  
Foundation