

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME Stl T.S. M/V MIRZA * Rpt. Ron No. 886

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

^{1st} Long Transverse No. 13935

Depth "d" 28.7'

Framing: Table No. ✓ Description Bull angle frames as approved

2nd Longitudinal No. 41385

Proportions Length 12.79
Depth =

~~Deck~~ Sheerstrake as approved

Revised Rule

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

* 100 A.I. (Steel). "Carrying Petroleum in bulk"
10" (Stl) Longitudinal framing at bottom and at deck
cell D.B u E 61' 272t, D.T. 28 305t, F.P.T. 210t, A.P.T. 87t.
F.K, 14 B.H, Lloyd's A R.P.
P 95', B 36', F 49'. machy app.

