

3-JUL 1963

Ship's name **ATHELSULTAN**

Port **WGM**

No. **699**

Last survey date **15/6/63**

Class is subject to **NIL**

Cracks found in m.e. frames ^{between} Nos 3 & 4
in welding & plates.

cracks veed out and welded up.

Surveyor recommends main engine

frame between Nos 3 & 4 units

(repaired by welding 6.63) be

re-examined by 8.63.



*It is submitted that this
vessel is eligible to remain
as CLASSED.* subject as recommended.



© 2020

Lloyd's Register
Foundation

3/7/63