

of Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME Stl & "CREEK FISHER" Report Liv No. 90551

**For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/82.*)

Survey Classification When due \_\_\_\_\_

100A — (Steel).

1 D<sup>x</sup> (Stl)

Cell D.B 103' 136t, F.P.T. 40t, A.P.T. 28t.

F.K, 3 B.H, Cmv,

Q 107' B 11' F 23'. machy aft.

DATE OF BUILD 1918.

8.26 Lan

S.S. Lan No 3 - 8.26



*[Signature]* 19.8.26.

Lloyd's Register  
Foundation

005118-005131-0005